



Follow-up Service Inspection Report MH46957U1191101084850

INSPECTION DETAILS			
Date:	2019-11-01	File Number.:	MH46957
Responsible Office:	Northbrook	Volume:	U1
Inspection Center:	763	CCN:	EGVV3
Product Type:	Dikes	UL Rep Name:	Carlo Winkel
Deliverable Type:	Unlisted	UL Rep ID:	34028
Party Site Number:	594525	Subscriber Factory No.:	679169-001
Manufacturer Name:	NCS RESINS (PTY) LTD	Factory Rep Name	Mr. Rohan Mohabir
Manufacturer Address:	9 Pineside Rd New Germany Kwazulu Natal	Factory Rep Phone:	+27-031-7130600
		Factory Rep Email:	rohanm@ncsresins.com
Nature of visit:	Regular Inspection	Sample Status:	Sample requirements fulfilled for sample period
UL Marks Used?	Yes	UL Marks Removed?	No
Variation Notice Issued?	No		
Comments After Submission:			

PRODUCT DOCUMENTS/PRODUCTION READY VISIT			
Model	Product	Section	Multiple Listed
33-404	Resin	1	No

SAMPLE DOCUMENTS			
If samples are required to be sent to ULI Laboratory, indicate below. If required samples are not sent, explain in the Comments area.			
No Samples			
Additional Comments			

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled "UL Mark Surveillance Requirements" that can be located at www.ul.com/fus, and in accordance with the applicable terms and conditions of the document at www.ul.com/responsibilities. Manufacturers without Internet access may obtain the current versions of these documents from their local UL customer service representative or UL field representative.